


毎日水質検査報告（給水栓）  
 令和8年2月 各施設 水温



|        | 1    | 2    | 3    | 4    | 5    | 6    | 7    | 8    | 9    | 10   | 11   | 12   | 13   | 14   | 15   | 16   | 17   | 18   | 19   | 20   | 21   | 22   | 23   | 24   | 25   | 26   | 27   | 28   |
|--------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|
| 石田配水場  | 8.5  | 8.6  | 8.4  | 8.4  | 8.7  | 9.1  | 8.7  | 8.5  | 8.2  | 7.9  | 8.1  | 8.7  | 8.4  | 8.4  | 8.7  | 9.6  | 9.1  | 9.2  | 9.2  | 9.3  | 8.8  | 9.0  | 9.3  | 9.4  | 9.6  | 9.6  | 9.8  | 9.9  |
| 洲本配水場  | 8.8  | 8.7  | 8.6  | 8.4  | 8.7  | 8.8  | 8.9  | 9.0  | 8.5  | 7.9  | 8.5  | 8.0  | 8.6  | 9.0  | 9.1  | 9.3  | 9.2  | 9.3  | 9.2  | 9.5  | 9.1  | 9.9  | 9.6  | 9.7  | 10.1 | 10.0 | 10.4 | 10.3 |
| 播磨田水源地 | 16.8 | 16.8 | 16.8 | 16.7 | 16.8 | 16.8 | 16.7 | 17.0 | 16.6 | 16.2 | 16.7 | 16.4 | 16.7 | 16.8 | 17.0 | 17.3 | 16.7 | 16.9 | 16.7 | 16.6 | 16.7 | 16.8 | 17.1 | 16.9 | 17.0 | 17.1 | 17.0 | 17.2 |
| 立入水源地  | 15.0 | 15.1 | 15.0 | 14.9 | 15.0 | 15.1 | 15.2 | 14.9 | 14.6 | 14.9 | 14.6 | 14.5 | 14.7 | 14.6 | 15.3 | 14.8 | 14.0 | 14.0 | 13.9 | 13.9 | 13.6 | 14.2 | 14.5 | 14.1 | 14.2 | 14.1 | 14.3 | 14.5 |







